
Current and Historic Surface Disturbance Features Caused by Coal Mining Activities in Logan and Mingo Counties, WV



Map showing areas of surface disturbance due to past and current coal mining activities and features. Active mine disturbance includes freshly exposed surfaces and active truck roads. Historical mine features include terraced hillsides with new growth vegetation. All of these features are associated with coal mining and coal refuse storage activities. The location and extent of these disturbances and features are useful to help predict the scale of needed reclamation efforts, as well as evaluate the potential for REE/CM resource development from this waste..